

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor Ted Stewart Executive Director James W. Carter Division Director

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax) 801-538-5319 (TDD)

February 13, 1995

Melvin Swanson Kelmine Corporation 2051 Swanson Circle Moab, Utah 84532

Re: Bond Release, Kelmine Corporation, Cub Mine, M/037/044, San Juan County, Utah

Thank you for your letter received January 17, 1995 regarding the reclamation status of the Cub Mine. We appreciate you notifying us that U.P. & L has removed the power pole at the site and that the vent shaft access road has been properly bermed. Has the road been adequately reclaimed, i.e. ripped, scarified and reseeded?

Before the surety can be fully released, we will need to perform an inspection of the site. We will plan on doing an inspection this spring as soon as weather permits. If you wish to attend the inspection, please contact me to schedule a convenient date and time.

Sincerely,

Anthony A. Gallegos Reclamation Engineer

Authory a. Sallego

jb

cc: Sal Venticinque, BLM, Grand RA

M037044

	× `•
-	



State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor Ted Stewart Executive Director James W. Carter Division Director

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax) 801-538-5319 (TDD)

September 9, 1993

Mr. Melvin R. Swanson 2051 Swanson Circle Moab, Utah 84532 7 1995 ON OF OIL, GAS & IMINING

Re: Cub Mine Bond Release, M/037/044, San Juan County, Utah

Dear Mr.Swanson:

Thank you for your letter dated August 17, 1993, explaining the status of the outstanding reclamation issues at the Cub site.

Please notify the Division when the UP&L power pole has been removed and the vent shaft access road reclaimed.

The 1950 decline falls outside the permitted area of the Cub mine, so the state has no jurisdiction to require reclamation. However, because it presents a safety hazard, it would be prudent for the claim holder to either reclaim it or gate/barricade it.

Sincerely,

1-7-95

Holland Shepherd

Senior Reclamation Specialist

jb where A vehicle can not get around it. A second trathen M037044

beam was ploud up from Road material at lower Imid point on Road, regain so no vehicles could get by it.

Both beams were placed with a CAT of ARE B-10 wide x 3-4 hed high. Upth has Removed the pole of the site

M. R. Luguen